


# No-Slack® H5092/X5092 Heavy Duty Series No-Slack® Top Plate Kits



## Repair

### Repair kit (KIT-RPR-5092L or R)

Item	Description	Qty.
①	Step jaw	1
②	Jaw and wedge spring	2
③	Cotter pin, 1/4" x 3"	2
④	Wedge	1
⑤	Bumper spring	1
⑥	Bushing, 5/16"	1
⑦	Hex lock nut, 1/2" - 13	1
⑧	Bushing, 7/16"	1
⑨	Hex lock nut, 1/2" - 13	1



### Wedge-stop rod kit (KIT-ROD-1108)

Item	Description	Quan.
⑩	Cotter pin, 3/16" x 1"	1
⑪	Wedge-stop rod	1
⑫	Flat washer, 5/8" I.D.	2
⑬	Wedge-stop rod spring	1
⑭	Wedge-stop rod nut	1



## Rebuild

### Part number: KIT-RX-5092L

Major rebuild kit for left side (driver) handle release H5092 and X5092 top plates.

Kit does not include bracket pins, bushings.



- Multiple kits combined in one saves you money
- Parts are arranged in the sequence you need them
- Complete instructions and link to video to make rebuild easy
- Reduce inventory
- Keep all the benefits of No-Slack® technology

**H5092 and X5092 top plates have been discontinued, however, parts are still available**

## Replace



### SLTPLH7 (Driver side)

#### No-Slack® H7 Heavy Duty Steel reinforced cast housing

Rated for extra heavy-duty to severe-duty in both on-highway and off-highway applications. It's also available as a blocked fifth wheel to accommodate frameless dump applications.

H7 is the recommended replacement for H5092 and X5092

- Excellent replacement for H5092 and X5092 fifth wheel top plates
- Mounts on existing H5092/X5092 slides and brackets
- 62,500 lbs to 70,000 lbs vertical load
- 150,000 lbs to 200,000 lbs drawbar pull
- Improved No-Slack® locking mechanism

